

## WSPGKIT12

## **GE 2X Winergy - Kit Contents**



## 9 of W61074881 Double phase springs 2 of W61074818

Brush springs wear out over time and should be replaced as a set.

Spring force may measure correctly but dynamic response can be sluggish.

Springs should be replaced every 3 to 5 years as a matched set.

Prevents uneven brush pressure and selectivity.

One box in the lift bag with all needed springs for one generator.

